HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

DEL. 3-SEFON.

Governor William H. Ross House State Route 543 Seaford vicinity Sussex County Delaware

Documentation: 16 exterior photos (1982) 3 interior photos (1982) 1 data page (1983)

Jack E. Boucher, Photographer

July, 1982

DE-196-1 SOUTH FRONT

DE-196-2 SOUTH FRONT CLOSER

DE-196-3 SOUTH FRONT FROM SOUTHWEST

DE-196-4 WEST SIDE AND SOUTH FRONT

DE-196-5 WEST SIDE

DE-196-6 WEST SIDE OF REAR WING

DE-196-7 NORTH SIDE FROM NORTHWEST .

DE-196-8 SOUTH FRONT FROM SOUTHEAST

DE-196-9 SOUTH FRONT FROM SOUTHEAST

DE-196-10 SOUTH FRONT FROM SOUTHEAST, CLOSER

DE-196-11 SOUTH FRONT FROM EAST

DE-196-12 EAST END OF SOUTH FRONT

DE-196-13 EAST END OF SOUTH FRONT, DETAIL OF FIRST-FLOOR WINDOWS

DE-196-14 WEST END OF SOUTH FRONT

DE-196-15 SOUTH FRONT, DETAIL OF DOORWAY

DE-196-16 WEST SIDE, DETAIL OF FIRST-FLOOR WINDOWS

DE-196-17 FIRST-FLOOR STAIR HALL, DETAIL OF NEWEL

DE-196-18 FIRST FLOOR, WEST ROOM, LOOKING NORTHWEST

DE-196-19 FIRST FLOOR, WEST ROOM, DETAIL OF WINDOW ON WEST WALL

DE-196

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS DEL, 3-SEFO.V, HABS No. DE-196 2-

ADDENDUM TO:
GOVERNOR WILLIAM H. ROSS HOUSE
State Route 543
Seaford Vicinity
Sussex County
Delaware

DE-196-1 through DE-200-19 were transmitted to the Library of Congress in 1983.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, July 1982

DE-196-20 (CT) SOUTH FRONT